

## LEADED GLASS CLEANING

LX-57B radiation shielding glass tends to tarnish more readily than ordinary window glass. Note the following points:

1. Wipe off smudges on the glass with a dry, clean cloth (e.g. gauze )  
NEVER USE A WET RAG
2. Wipe fingerprints off the glass immediately with a dry, clean cloth.
3. Smudges not removable by wiping with a dry cloth should be cleaned with a cloth and isopropyl alcohol.
4. Window must be completely dried to avoid streaking.